# **MERITOR® TIRE INFLATION** SYSTEM (MTIS<sup>TT</sup>) DIAGNOSTICS **POTENTIAL ISSUES AND SOLUTIONS**

# LUBRICANT HAS STAINED THE THRU-TEE.

## The wheel-end is overfilled with lubricant.

- A. If the thru-tee is stained with oil, determine first if it is a result of an overpacked wheel-end. If the wheel-end is overpacked, when the hub heats up it will force oil out of the hub cap vents. This is not a MTIS system malfunction.
- B. Refill the wheel-end with the correct amount of lubricant.

A hubcap without vent extensions is installed onto an oil-lubricated wheel-end, staining the thru-tee. Install a hubcap with vent extensions.

# THE WARNING LIGHT IS ON.

## The system is delivering air during initial system charging.

The system is functioning correctly. Note: if the warning light is ON for more than 10 minutes after start-up, inspect wheel-end components

# The system is delivering air to a leaking tire.


- A. Remove the tire inflation system hose at the thru-tee.
- B. Press the tire pressure gauge to the hose and read the pressure.
- **C.** If the tire pressure is correct, reconnect the hose to the thru-tee by hand-tightening the knurled fitting. Do not tighten with pliers.
- D. If the tire pressure is not correct, repair or replace the tire.

# The system is delivering air to a leaking system component.

- A. Apply a non-corrosive leak finding solution to all air hose connections (thru-tee, tire valve stem, control box hoses and valves, axle air fitting and tees) \*if applicable
- B. If a leak is located, replace the malfunctioning component.
- C. To check for leaks on an internal axle component, apply a non-corrosive leak-finding solution to the hub cap relief valve.
- D. If a leak is identified, turn ON the shut-off valve at the control box and drain the air using the drain petcock. Remove the thru-tee and hub cap.
- E. Place a cloth around the spindle to protect the inner wheel-end components from contamination, and reinsert the thru-tee into the stator. Turn OFF the shutoff valve at the control box to allow airflow. Apply a non-corrosive leak finding solution to the thru-tee, stator, ThermALERT plug and axle press plug. Listen and watch for bubbling. Tighten or replace components as determined. Refer to maintenance manual MM14P for recommended repair and installation guidelines.

## The system wiring is incorrect.

Correct the system wiring. Refer to manual 14P (MM14P) for proper wiring instructions.



The trailer is not supplied with 12-volt power. Supply 12-volt power to the trailer.

The warning light is inoperative. Replace the warning light.

The flow sensing switch is inoperative. Replace the flow sensing switch.

The system wiring is damaged. Repair the system wiring.

# The system wiring is incorrect.

Correct the system wiring. Refer to manual 14P (MM14P) for proper wiring instructions

# TIRE PRESSURE IS LOW.

# The shut-off valve is on.

Turn off the shut-off valve to allow airflow.

# The system pressure setting is too low.

Increase the system pressure setting. Follow manual 14P (MM14P) guidelines for proper regulator adjustment procedures.

# The hoses have incorrect valve cores installed.

# Replace the hoses with Meritor original

equipment. The system is delivering air to a leaking system component.

Tighten or replace following manual 14P (MM14P) instructions.


# TIRE PRESSURE IS HIGH.

The tire is manually over-inflated.


Reduce the tire pressure. The system will inflate to the correct level.

## The system pressure setting is too high.


Follow the regulator adjustment procedures in manual MM14P to adjust tire pressure to target pressure setting.




OIL LEVEL BELOW THE HUBCAP WHEEL-END VENTS





THERMAL PLUG













- 12V DC power to 7 pin connector
- External air supply (120 PSI minimum)
- Current detector
- Clean cloth
- Spray bottle with non-corrosive leak finding solution (soapy water)
- Tire pressure gauge (high quality preferred)



Meritor original equipment parts are required when servicing the tire inflation system. Non-original parts may fit the system, but can prevent the system from functioning properly. Damage to components can result.