


# EX+™ DRIVER PRE-TRIP INSPECTION



**MERITOR**



Air Chamber  
and Connection

3

Rotor  
2

Visual Wear  
Indicator  
1

Adjuster Cover 5

Caliper Bolts 4

Slide Pin Caps 6

**1****Visual Wear Indicator**

If the indicator shows more than 75% wear, perform wheels-off inspection. (Figure 1)

**2****Rotor**

Visually inspect the rotor for signs of cracks, deep grooves, blue marks and heat checking.

**3****Air Chamber and Connection**

Inspect the air chamber to verify that the air chamber-to-caliper mounting nuts and air lines are securely fastened and are not damaged.

**4****Caliper Bolts**


Visually inspect the caliper mounting bolts and ensure all 6 bolts are present.

**5****Adjuster Cover**

Visually inspect for caliper adjuster cover. If missing, replace with new cover.

**6****Slide Pin Caps**

Visually inspect the slide pin caps, if missing, further inspection of the slide pins and bushings is needed.

**Figure 1**

4010454a

Reference MM0467 at [meritor.com/lod](http://meritor.com/lod) for more information.



Meritor Heavy Vehicle Systems, LLC  
2135 West Maple Road  
Troy, Michigan 48084 USA

Call 1-866-668-7221  
or visit [meritor.com](http://meritor.com).

©2019 Meritor, Inc.  
Litho in USA  
TP-1938