






# MERITOR® TIRE INFLATION SYSTEM (MTIS™) MANIFOLD CONTROL BOX SERVICE PARTS



Part #	Description	
31104-00	Filter Element	
31105-00	Clear Filter Bowl Kit, includes: ■ Bowl and seal  (Note: Remove old seal from manifold before replacing with new seal.)	
31084-14	Manifold Service kit, includes: ■ 1 pc manifold assembly ■ 1 pc manifold gasket ■ 4 pcs mounting screws and washers ■ 1 pc air line	
31083-33	Control Box Enclosure Assembly, includes: ■ Empty box ■ Lid with lid screws, gasket and decals affixed on inside of lid	
31083-28	Control Box Lid Assembly, includes: ■ Lid with lid screws, gasket and decals affixed on inside of lid	

Trademarks, brands, and names depicted herein are the property of Meritor, Inc. or its affiliates.



Meritor Heavy Vehicle Systems, LLC  
7975 Dixie Highway  
Florence, Kentucky 41042 USA

888-725-9355 US  
800-387-3899 Canada  
MeritorPartsXpress.com  
meritor.com

©2020 Meritor, Inc.  
Litho in USA, SP-20105  
Issued 03-20 (82099)