

# Service Parts Instructions

## Installing Lining Anti-Rattle Springs on Meritor's 2.88-Inch Twin-Piston Caliper Assembly Meritor Kit XXX



#### WARNING

To prevent serious eye injury, always wear safe eye protection when you perform vehicle maintenance or service.



## ASBESTOS AND NON-ASBESTOS FIBERS WARNING

Some brake linings contain asbestos fibers, a cancer and lung disease hazard. Some brake linings contain non-asbestos fibers, whose long-term effects to health are unknown. You must use caution when you handle both asbestos and non-asbestos materials.

For complete maintenance and service instructions for installing lining anti-rattle springs on Meritor's 2.88-inch twin-piston caliper assembly, refer to Maintenance Manual XX. Call ArvinMeritor's Customer Service Center at 800-535-5560 to order this publication or visit the Tech Library section at arvinmeritor.com at the following address.


arvinmeritor.com/tech\_library/home.asp


## **Kit XXX Contents**

- Anti-rattle spring Part number 69160441/445
- \_

### **Installation Procedure**

- Place an anti-rattle spring on top of the linings.
  Figure 1.
- 2. Press the ends of the spring down between the linings and into the notches in the underside of the caliper. **Figure 2**.







Commercial Vehicle Aftermarket 7975 Dixie Highway Florence, KY 41042 USA 606-525-3500 arvinmeritor.com



Information contained in this publication was in effect at the time the publication was approved for printing and is subject to change without notice or liability. ArvinMeritor Commercial Vehicle Systems reserves the right to revise the information presented or discontinue the production of parts described at any time.