

# MERITOR® AIR DISC BRAKE ROTORS FOR THE AFTERMARKET




# WE START WITH THE RIGHT STUFF. AND STOP WITH IT, TOO.

Meritor® Air Disc Brake (ADB) rotors are designed for enhanced thermal properties to extend life and improve fade resistance.

- Lower temperatures during braking allow for longer friction life and improved rotor durability.


Meritor cooling vanes on all-makes aftermarket rotors use the same cooling vane design as Meritor Genuine first fit rotors that are specified for OE use.

- Cooling vanes promote air flow through the rotor and reduce overall rotor weight.



Meritor® ADB rotors are engineered with high quality cast iron. The formulation and process produces long graphite flakes which conduct heat.

- Better thermal dissipation provides lower peak temperatures for longer friction life.



U-SHAPED ROTOR						
Meritor Part Number	Application	Vocation	Outside Disc	New Disc Thickness	Discard Thickness	Overall Rotor Depth
M44DHS34471	Hendrickson® Maxx™ 22T	Trailer	16.3"	1.7"	1.5"	5.9"
M44DK021958	Bendix® SN7™	Linehaul / Vocational	16.9"	1.8"	1.5"	3.4"
M44D37415	Bendix® SN7™	Transit / Coach	16.9"	1.8"	1.5"	3.6"
M44D802081	Bendix® ADB22X™	Trailer / Linehaul / Refuse	16.9"	1.8"	1.5"	5.4"
M44DHS34172006	Hendrickson Maxx 22T	Trailer (ABS ring flush with disc)	16.9"	1.8"	1.5"	5.9"
M44D802082	Bendix® ADB22X™	Trailer / Linehaul / Refuse (no ABS ring)	16.9"	1.8"	1.5"	5.9"
M44DHCT807	WABCO®	Trailer (ABS ring inset by 1 1/16")	16.9"	1.8"	1.5"	5.4"
M44DH20682	ConMet® EX+ L / WABCO® Maxxus™	Trailer	16.9"	1.8"	1.5"	6.3"
M44DHK021959	Prevost	Coach	16.9"	1.8"	1.5"	7.1"
M44D23642	Meritor®	Refuse and Coach	17.1"	1.8"	1.5"	5.2"
HAT-SHAPED ROTOR						
M44DK034497	Bendix® SN7™	Trailer / Coach	16.9"	1.8"	1.5"	4.1"
M44D802669	Bendix® SN7™	Trailer / Coach	16.9"	1.8"	1.5"	4.5"
FLAT-SHAPED ROTOR						
M44DH802569	Bendix® Splined	Truck / Trailer	16.9"	1.8"	1.5"	1.8"
M44DH18609	ConMet EX+ L / WABCO Pan™ 22 / Hendrickson Maxx 22T	Trailer	16.9"	1.8"	1.5"	2.1"
M44DH83924	ConMet Flat with press-on tone ring	Truck Front (press-on tone ring)	16.9"	1.8"	1.5"	2.1"
M44DH83923	ConMet Flat with bolt-on tone ring	Truck Rear (press-on tone ring)	16.9"	1.8"	1.5"	2.1"

# COMPETITIVE CROSS-REFERENCE

U-SHAPED ROTOR		
Make	Part Number	Meritor Part Number
Bendix®	802081, K000758, K038573	<b>M44D802081</b>
	802082, K000332, K038574, K110358	<b>M44D802082</b>
	I1371910061, K021958	<b>M44DK021958</b>
	I137415N	<b>M44D37415</b>
	K021959, 1137986	<b>M44DHK021959</b>
Celerity®	CSD17A01	<b>M44D802081</b>
	CSD17A02	<b>M44D802082</b>
	CSD17A03	<b>M44DK021958</b>
	CSD17A05	<b>M44D37415</b>
	CSD17A08	<b>M44DHK021959</b>
Centric®	120.86003	<b>M44D802081</b>
	120.86004	<b>M44D37415</b>
	120.86005	<b>M44DHK021959</b>
	120.86006	<b>M44D802082</b>
	120.86009	<b>M44DK021958</b>
ConMet®	10020109, 10020682	<b>M44DH20682</b>
	10041006, 10082074	<b>M44D802082</b>
Coolrun	BR61-1457	<b>M44DHK021959</b>
DuraBrake®	76603	<b>M44D37415</b>
	76604	<b>M44DHK021959</b>
	76612	<b>M44DK021958</b>
	76613	<b>M44DHCT807</b>
	76617	<b>M44D802082</b>
	76618	<b>M44D802081</b>
	76619	<b>M44DHS34172006</b>
Hendrickson	S-32193	<b>M44D802082</b>
	S-34172	<b>M44DHS34172006</b>
	S-34471	<b>M44DHS34471</b>
MCI	04-04-1107, 15-02-1081	<b>M44DK021958</b>
Meritor®	M44D76604	<b>M44DHK021959</b>
	M44D76612	<b>M44DK021958</b>
	M44D76617	<b>M44D802082</b>
	M44D76618	<b>M44D802081</b>
	M44D76619	<b>M44DHS34172006</b>
New Flyer®	6407925	<b>M44DK021958</b>
NOVABUS®	N8884457	<b>M44DK021958</b>
Prevost®	611547, 621672	<b>M44DHK021959</b>
Van Hool	920924972	<b>M44DK021958</b>

U-SHAPED ROTOR (cont'd)		
Make	Part Number	Meritor Part Number
Volvo®	56022P	<b>M44D37415</b>
	1137986	<b>M44DHK021959</b>
WABCO®	1660363	<b>M44DHS34172006</b>
Webb®	56024P	<b>M44DK021958</b>
	56050P	<b>M44DHK021959</b>
	56090PK	<b>M44DH20682</b>
	56095P	<b>M44D802082</b>
	56096P	<b>M44D802081</b>
ZF®	55097P	<b>M44DHS34172006</b>
	0501.316.953	<b>M44DK021958</b>
HAT-SHAPED ROTOR		
Make	Part Number	Meritor Part Number
Bendix®	802669, Z006407	<b>M44D802669</b>
	K034497	<b>M44DK034497</b>
Celerity	CSD17A09	<b>M44DK034497</b>
	CSD17A11	<b>M44D802669</b>
Centric	120.86008	<b>M44D802669</b>
DuraBrake	76641	<b>M44D802669</b>
	76642	<b>M44DK034497</b>
Meritor	M44D76641	<b>M44D802669</b>
	M44D76642	<b>M44DK034497</b>
Prevost	611300	<b>M44D802669</b>
Webb	55080P	<b>M44D802669</b>
FLAT-SHAPED ROTOR		
Make	Part Number	Meritor Part Number
Bendix®	802569	<b>M44DH802569</b>
ConMet	10016195, 10018609	<b>M44DH18609</b>
	10025445, 10023879	<b>M44DH802569</b>
	10083923	<b>M44DH83923</b>
	10083924	<b>M44DH83924</b>
Celerity	CSD17A04	<b>M44DH802569</b>
Centric	120.86017	<b>M44DH802569</b>
DuraBrake	76692	<b>M44DH802569</b>
Hendrickson	S-29152-17	<b>M44DH802569</b>
SAF Holland	03079001501Z	<b>M44DH802569</b>
Webb	56092PK	<b>M44DH18609</b>
	56094PK	<b>M44DH802569</b>

## You Deserve Complete Support

Meritor air disc brake rotors are covered by our complete 1-year warranty. Meritor's industry-leading Customer Care team provides an all-purpose, one-call solution for customer satisfaction. For more information, call our U.S. Customer Care Center at 888-725-9355. In Canada, call 800-387-3889. Or visit [MeritorPartsXpress.com](http://MeritorPartsXpress.com).



Vehicle models, trademarks, brands, and names depicted herein are the property of their respective owners, and may not be associated with Cummins Inc. and Meritor, Inc. or its affiliates.



Cummins Inc.  
Box 3005  
Columbus, IN 47202-3005  
U.S.A.

[cummins.com](http://cummins.com) | [MeritorPartsXpress.com](http://MeritorPartsXpress.com)

SP-2006  
Bulletin 6471382 Produced in U.S.A. Rev. 4/23  
©2023 Meritor, Inc.