

MERITOR® HYDRAULIC BRAKE ROTORS WITH PLATINUMSHIELD™ II COATING



MERITOR

 **IDEAS DRIVING RESULTS**

ADVANCED PROTECTIVE COATING FOR
SUPERIOR SERVICE LIFE.





Meritor hydraulic brake rotors are protected with PlatinumShield II – a patented, proprietary coating designed to protect against oxidation and corrosion. Thoroughly tested to withstand the harshest road conditions, these rotors are ideal for a wide variety of medium-duty vehicles, such as school buses, emergency vehicles and delivery trucks.


Features and Benefits:

- Patented technology prevents substances such as rock salt, magnesium chloride, calcium chloride and other chemicals from rusting brake rotors
- Proprietary coating thoroughly seals the rotor – even the outside edge of the cooling veins – to prevent corrosion and metal fatigue
- The coating will not wear or chip when exposed to heat, chemical de-icers, wash solutions, pebbles, sand or grime
- A unique coating process ensures that the rotor receives a complete application while exacting tolerances and thermal properties are maintained
- The special coating delivers optimum rotor performance and service life for medium-duty truck, school bus and express delivery applications
- Rigorous testing on the road and in the lab – including 400 hours of salt-spray testing – has shown significantly improved service life over uncoated rotors
- Hydraulic brake rotors with rust-resistant coating are backed by a 1-Year/100,000-Mile warranty



Designed and built to exacting specifications

Machine-to-Balance (MTB) process eliminates drive-in weights for balancing



Coating applied to key contact points to prevent rust from spreading to hub and wheel

ABS teeth and veins are coated to maintain ABS tone ring integrity



Product models, brands and names depicted herein are the property of their respective owners and are not in any way associated with Meritor, Inc., or its affiliates.



Meritor Heavy Vehicle Systems, LLC
7975 Dixie Highway
Florence, Kentucky 41042 USA

888-725-9355 U.S.
800-387-3889 Canada
MeritorPartsOnline.com
meritor.com

©2015 Meritor, Inc.
Litho in USA, SP-1043
Revised 02-15 (47865/11900)